

**P H C A A 0 0 3 - B C D E V**

To create an ordering code fill in the boxes above with the appropriate number and/or letter from the corresponding box below.

**Box A: Recording Points**

33 = 3 continuous recording	\$ 2,199
66 = 6 continuous recording	2,255
76 = 6 dotting recording	2,475

**Box B: Power Supply**

A = 85-150V AC 50/60Hz	N/C
E = 150-300V AC 50/60Hz	N/C

**Box C: Chart Paper Illumination**

A = Without	N/C
B = With	\$ 290

**Box D: Alarm Output/Ext. Control**

0 = Without	N/C
1 = 6-point alarm output/3-point external control	350

**Box E: Transmission Function**

Y = Without	N/C
R = With RS-485	470

**ACCESSORIES & SPARE PARTS**

PHZK8601	Alarm output/external control unit for the PHA series with 6-point alarm output/3-point external control	\$ 350
PHZK8701	Alarm output/external control unit for the PHA series with 12-point alarm output/3-point external control	640
PHZK1601	Alarm output/external control unit for the PHC series	350
PHZH1001	Recording head	145
PHZL8001	Chart illumination lamp for the PHA	180
PHZL1001	Chart illumination lamp for the PHC	150
PEX00BL1-1000B	Chart paper for the PHA (1 set = 6 pkgs. of paper)	100
PEX00DL1-5000B	Chart paper for the PHC (1 set = 6 pkgs. of paper)	100
SHUNT RESISTOR	10Ω or 250Ω shunt resistor	4.25

Information subject to change without notice. Prices in USD. 011110